

**Flood Control Project Maintenance
Levee Inspections
2008 Channel Summary Report
Overall Unit and Item Ratings**

DWR Sutter Maintenance Yard

Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Big Chico Creek

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Channel Rating	A

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel						Inspection Date	Inspector	
Big Chico Creek						09/17/2008	Bob Duffey	
Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.761840 ° 121.792590 °	Y	1
2	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.747000 ° ,601.000000 °	Y	2
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.738490 ° 121.822810 °	Y	3
4	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.738490 ° ,281.000000 °	Y	4
5	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.731810 ° 121.841870 °	Y	5
6	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.725860 ° 121.851360 °	Y	6
7	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.704580 ° 121.939320 °	Y	7
8	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.704580 ° 121.939320 °	Y	8

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Big Chico Creek	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from the big Chico Creek Control Structure.



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from bridge near Forest Avenue heavy growth along both banks.



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Hwy. 99 growth along both banks.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Big Chico Creek	09/17/2008	Bob Duffey

Report Line	4
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Hwy 99 dense vegetation in channel.



Report Line	5
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from the Esplanado heavy growth on both banks.



Report Line	6
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Hwy. 32 heavy growth on both banks.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Big Chico Creek	09/17/2008	Bob Duffey

Report Line	7
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream approximately 500 feet from the confluence with the Sacramento River.



Report Line	8
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream towards the confluence with the Sacramento River.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Lindo Channel

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Channel Rating	A

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel					Inspection Date	Inspector		
Lindo Channel					09/17/2008	Bob Duffey		
Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.761590 ° 121.797320 °	Y	1
2	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.760510 ° 121.802070 °	Y	2
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.755400 ° 121.814580 °	Y	3
4	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.752730 ° 121.824560 °	Y	4
5	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.749380 ° 121.854400 °	Y	5
6	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.741190 ° 121.881380 °	Y	6
7	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.735560 ° 121.890970 °	Y	7
8	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.722700 ° 121.912520 °	Y	8

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Lindo Channel	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from the Lindo Channel Diversion Structure.



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Manzanita Avenue.



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from the bike path bridge at the extension of Madrone Avenue.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Lindo Channel	09/17/2008	Bob Duffey

Report Line	4
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Mariposa.



Report Line	5
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from the Esplanade.



Report Line	6
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Hwy. 32.

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Lindo Channel	09/17/2008	Bob Duffey

Report Line	7
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Oak Avenue.



Report Line	8
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Grape Way heavy vegetation.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Little Chico Creek

Date of Inspection	9/17/2008
DWR Inspector	Bob Duffey
Channel Rating	A

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Little Chico Creek	09/17/2008	Bob Duffey

Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.733890 ° 121.771940 °	Y	1
2	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.733020 ° 121.787580 °	Y	2
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.737400 ° 121.804530 °	Y	3
4	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.735670 ° 121.814510 °	Y	4
5	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.730240 ° 121.823800 °	Y	5
6	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A		39.726800 ° 121.829870 °	Y	6
7	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.724840 ° 121.833520 °	Y	7
8	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.703260 ° 121.868470 °	Y	8
9	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		M		39.703260 ° 121.868470 °	Y	9

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected


Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Little Chico Creek	09/17/2008	Bob Duffey

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from the control structure on Little Chico Creek.



Report Line	2
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Bruce Road.



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Forest Avenue heavy vegetation.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Little Chico Creek	09/17/2008	Bob Duffey

Report Line	4
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Erosion repair site, upstream of Hwy.99.



Report Line	5
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Boucher Street dense growth on both banks.



Report Line	6
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Olive Street.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Channel 2008

DWR Sutter Maintenance Yard

Channel	Inspection Date	Inspector
Little Chico Creek	09/17/2008	Bob Duffey

Report Line	7
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream from Broadway Street heavy growth on both banks.	



Report Line	8
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Upstream from Lone Pine Street large oak in channel.	



Report Line	9
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream from Lone Pine Street heavy growth on both banks.	

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable

PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected

C : Corrected